



Information Letter TTC-IL-DHC3-01

August 25, 2005

Dear Super Otter Owner:

This letter is to inform you that Texas Turbine Conversions, Inc. has received two reports of reduced forward visibility in Super Otters during flight in heavy rain. TTC, Inc. is investigating the reports and would appreciate any feedback from operators who run, or have run, both the piston Otter and the Super Otter. We are trying to determine if this is a characteristic of the original Otter or not.

Numerous other aircraft over the years have exhibited similar characteristics and operators of those aircraft recommend using a rain repellent product on the windshield such as Rain-X, etc. They state that it makes a significant difference in the forward visibility in heavy rain.

TTC, Inc. will continue to investigate the issue and will appreciate any feedback from operators either via telephone, fax, or email. We can be contacted as follows:

Telephone: (972) 382-4402
Fax: (972) 382-4410
Email: texasturbines@aol.com

* * * * *