



Information Letter TTC-IL-DHC3-02

August 25, 2005

Dear Super Otter Owner:

This letter is to inform you that Texas Turbine Conversions, Inc. has issued service bulletin TTC-SB-DHC-02 on this date affecting the primary exhaust nozzle P/N 34264. The service bulletin details inspection and repair criteria for the exhaust. TTC, Inc. is working on a modification to the exhaust that could hopefully prevent further cracking problems and relieve the repetitive inspections. TTC, Inc. appreciates any feedback from operators either via telephone, fax, or email. We can be contacted as follows:

Telephone: (972) 382-4402
Fax: (972) 382-4410
Email: texasturbines@aol.com

* * * * *